Wood Destroying Insect Inspection Report						
Wood Destroying insect inspection Report	Notice: Please read important consumer i	information	on page 2.			
Section I. General Information Inspection Company, Address & Phone	Company's Pest Control Business Lic. No 02714-001		Date of Inspection 2025-11-25			
Preferred Pest Management 2725 Ford Street	Address of Property Inspected					
Ames, IA 50010	15112 NE 72ND ST					
(515) 292-8989	Cambridge, IA 50046					
Inspector's Name, Signature & Certification, Registration, or Lic. #		Structure(s	s) Inspected			
Emory Arentson 3Q 1338	0	,	nd attached garage.			
Section II. Inspection Findings This report is indicative of the condition of the above identified structure(s) on the date of inspection ad is not to be construed as a guarantee or warranty against latent, concealed, or future infestations or wood destroying insect damage. Based on a careful visual inspection of the readily accessible areas of the structure(s) inspected:						
[X] A. No Visible evidence of wood destroying insects was observed.						
[] B. Visible evidence of wood destroying insects was observed.						
[] 1. Live insects (description & location):						
[] 2. Dead insects, insect parts, frass, shelter tubes, exit holes, or staining (description and location):						
[] 3. Visible damage from wood destroying insects was noted as follows (description and location):						
NOTE: This is not a structural damage report. If box B above is checked, it should be used any questions arise regarding damage indicated by this report, it is recommended that the bus	_	_				
of damage and the need for repairs.	yer or any interested parties contact a	quaiilleu s	udctural professional to determine the extent			
Section III. Recommendations						
[X] No action and/or treatment recommended: (Explain if Box B in Section II is checked):						
[] Recommended action(s) and/or treatment(s) for the control of:						
Section IV. Obstructions and Inaccessible Areas The following areas of the structure(s) inspected were obstructed or inaccessible:		the follow	ector may write out obstructions or use wing optional key:			
[X] Basement Except utility room ceiling and interior walls: 1, 3		Fixed ceil Suspende	ed ceiling 16. Dense vegetation			
[] Crawlspace		Fixed wal Floor cov				
[] Main Level	[] Main Level					
[] Attic			19. Wood pile			
[] Attic		5. Insulation6. Cabinets7. Stored ite8. Furnishin	19. Wood pile or shelving 20. Snow ums 21. Unsafe conditions			
[] Attic		6. Cabinets 7. Stored ite 8. Furnishin 9. Appliance	19. Wood pile or shelving 20. Snow 21. Unsafe conditions gs 22. Rigid foam board as 23. Synthetic stucco			
		6. Cabinets 7. Stored ite 8. Furnishin 9. Appliance 10. No acce 11. Limited	19. Wood pile or shelving 20. Snow mms 21. Unsafe conditions gs 22. Rigid foam board us 23. Synthetic stucco sss or entry 24. Duct work, wiring, and/or plumbing			
[X] Garage : 1, 3		6. Cabinets 7. Stored ite 8. Furnishin 9. Appliance 10. No acce 11. Limited a 12. No acce 13. Only vis	19. Wood pile or shelving 20. Snow gs 21. Unsafe conditions gs 22. Rigid foam board es 23. Synthetic stucco sss or entry 24. Duct work, wiring, and/or access plumbing ss beneath 25. Spray foam insulation ual access 26. Equipment			
[X] Garage : 1, 3		6. Cabinets 7. Stored ite 8. Furnishin 9. Appliance 10. No acce 11. Limited a 12. No acce	19. Wood pile or shelving 20. Snow gs 21. Unsafe conditions gs 22. Rigid foam board es 23. Synthetic stucco sss or entry 24. Duct work, wiring, and/or access plumbing ss beneath 25. Spray foam insulation ual access 26. Equipment			
[X] Garage : 1, 3 [] Exterior [] Porch		6. Cabinets 7. Stored ite 8. Furnishin 9. Appliance 10. No acce 11. Limited a 12. No acce 13. Only vis	19. Wood pile or shelving 20. Snow gs 21. Unsafe conditions gs 22. Rigid foam board es 23. Synthetic stucco sss or entry 24. Duct work, wiring, and/or access plumbing ss beneath 25. Spray foam insulation ual access 26. Equipment			
[X] Garage : 1, 3 [] Exterior [] Porch [] Addition [] Other		6. Cabinets 7. Stored ite 8. Furnishin 9. Appliance 10. No acce 11. Limited a 12. No acce 13. Only vis	19. Wood pile or shelving 20. Snow gs 21. Unsafe conditions gs 22. Rigid foam board es 23. Synthetic stucco sss or entry 24. Duct work, wiring, and/or access plumbing ss beneath 25. Spray foam insulation ual access 26. Equipment			
[X] Garage: 1, 3 [] Exterior [] Porch [] Addition		6. Cabinets 7. Stored ite 8. Furnishin 9. Appliance 10. No acce 11. Limited a 12. No acce 13. Only vis	19. Wood pile or shelving 20. Snow gs 21. Unsafe conditions gs 22. Rigid foam board es 23. Synthetic stucco sss or entry 24. Duct work, wiring, and/or access plumbing ss beneath 25. Spray foam insulation ual access 26. Equipment			
[X] Garage : 1, 3 [] Exterior [] Porch [] Addition [] Other		6. Cabinets 7. Stored ite 8. Furnishin 9. Appliance 10. No acce 11. Limited a 12. No acce 13. Only vis	19. Wood pile or shelving 20. Snow gs 21. Unsafe conditions gs 22. Rigid foam board es 23. Synthetic stucco sss or entry 24. Duct work, wiring, and/or access plumbing ss beneath 25. Spray foam insulation ual access 26. Equipment			
[X] Garage : 1, 3 [] Exterior [] Porch [] Addition [] Other		6. Cabinets 7. Stored ite 8. Furnishin 9. Appliance 10. No acce 11. Limited a 12. No acce 13. Only vis	19. Wood pile or shelving 20. Snow gs 21. Unsafe conditions gs 22. Rigid foam board es 23. Synthetic stucco sss or entry 24. Duct work, wiring, and/or access plumbing ss beneath 25. Spray foam insulation ual access 26. Equipment			
[X] Garage : 1, 3 [] Exterior [] Porch [] Addition [] Other		6. Cabinets 7. Stored ite 8. Furnishin 9. Appliance 10. No acce 11. Limited a 12. No acce 13. Only vis	19. Wood pile or shelving 20. Snow gs 21. Unsafe conditions gs 22. Rigid foam board es 23. Synthetic stucco sss or entry 24. Duct work, wiring, and/or access plumbing ss beneath 25. Spray foam insulation ual access 26. Equipment			
[X] Garage : 1, 3 [] Exterior [] Porch [] Addition [] Other		6. Cabinets 7. Stored ite 8. Furnishin 9. Appliance 10. No acce 11. Limited a 12. No acce 13. Only vis	19. Wood pile or shelving 20. Snow gs 21. Unsafe conditions gs 22. Rigid foam board es 23. Synthetic stucco sss or entry 24. Duct work, wiring, and/or access plumbing ss beneath 25. Spray foam insulation ual access 26. Equipment			
[X] Garage : 1, 3 [] Exterior [] Porch [] Addition [] Other Section V. Additional Comments and Attachments (these are an integral	I part of the report)	6. Cabinets 7. Stored ite 8. Furnishin 9. Appliance 10. No acce 11. Limited 12. No acce 13. Only vis 14. Cluttere	19. Wood pile or shelving 20. Snow uns 21. Unsafe conditions ups 22. Rigid foam board ups 23. Synthetic stucco 24. Duct work, wiring, and/or plumbing ups beneath ual access d condition 25. Spray foam insulation ual access d condition			
[X] Garage: 1, 3 [] Exterior [] Porch [] Addition [] Other Section V. Additional Comments and Attachments (these are an integral and attachments) Attachments Signature of Seller(s) or Owner(s) if refinancing. Seller discloses to the buyer all information, to their knowledge, regarding W.D.I. infestation, damage, repair, and treatment	I part of the report) Signature of Buyer. The under	6. Cabinets 7. Stored ite 8. Furnishin 9. Appliance 10. No acce 11. Limited 12. No acce 13. Only vis 14. Cluttere	19. Wood pile or shelving 20. Snow uns 21. Unsafe conditions ups 22. Rigid foam board ups 23. Synthetic stucco 24. Duct work, wiring, and/or plumbing ups beneath ual access d condition 25. Spray foam insulation ual access d condition			
[X] Garage: 1, 3 [] Exterior [] Porch [] Addition [] Other Section V. Additional Comments and Attachments (these are an integral and attachments) Attachments Signature of Seller(s) or Owner(s) if refinancing. Seller discloses to the buyer all information, to their knowledge, regarding W.D.I. infestation, damage, repair, and treatment	I part of the report) Signature of Buyer. The under	6. Cabinets 7. Stored ite 8. Furnishin 9. Appliance 10. No acce 11. Limited 12. No acce 13. Only vis 14. Cluttere	19. Wood pile or shelving 20. Snow uns 21. Unsafe conditions ups 22. Rigid foam board ups 23. Synthetic stucco 24. Duct work, wiring, and/or plumbing ups beneath ual access d condition 25. Spray foam insulation ual access d condition			

Important Consumer Information Regarding the Scope and Limitations of the Inspection

Please read this entire page as it is part of this report. Please refer to the NPMA Suggested Guidelines for instructions on completing this report. This report is not a guarantee or warranty as to the absence of wood destroying insects nor is it a structural integrity report. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair.

- 1. About the Inspection: A visual inspection was conducted in the readily accessible areas of the structure(s) indicated (see Page 1) including attics and crawlspaces which permitted entry during the inspection. The inspection included probing and/or sounding of unobstructed and accessible areas to determine the presence or absence of visual evidence of wood destroying insects. The WDI inspection firm is not responsible to repair any damage or treat any infestation at the structure(s) inspected, except as may be provided by separate contract. Also, wood destroying insect infestation and/or damage may exist in concealed or inaccessible areas. The inspection firm cannot guarantee that any wood destroying insect infestation and/or damage disclosed by this inspection represents all of the wood destroying insect infestation and/or damage which may exist as of the date of the inspection. For purposes of this inspection, wood destroying insects include: termites, carpenter ants, carpenter bees, and reinfesting wood boring beetles. This inspection does not include mold, mildew or noninsect wood destroying organisms. This report shall be considered invalid for purposes of securing a mortgage and/or settlement of property transfer if not used within ninety (90) days from the date of inspection. This shall not be construed as a 90-day warranty. There is no warranty, express or implied, related to this report unless disclosed as required by state regulations or a written warranty or service agreement is attached.
- 2. Treatment Recommendation Guidelines Regarding Subterranean Termites: Treatment or corrective action should be recommended if live termites are found. If no evidence of a previous treatment is documented and evidence of infestation is found, even if no live termites are observed, treatment or corrective action by a licensed pest control company should be recommended. Treatment or corrective action may be recommended if evidence of infestation is observed, and a documented treatment occurred previously, unless the structure is under warranty or covered by a service agreement with a licensed pest control company.
 For other Wood Destroying Insects, please refer to the NPMA suggested guidelines for added guidance on actions and or treatment.
- 3. **Obstructions and Inaccessible Areas:** No inspection was made in areas which required the breaking apart or into, dismantling, removal of any object, including but not limited to: moldings, floor coverings, wall coverings, siding, fixed ceilings, insulation, furniture, appliances, and/or personal possessions; nor were areas inspected which were obstructed or inaccessible for physical access on the date of inspection. Your inspector may write out inaccessible areas or use the key in Section IV. Crawl spaces, attics, and/or other areas may be deemed inaccessible if the opening to the area is not large enough to provide physical access for the inspector or if a ladder was required for access. Crawl spaces (or portions thereof) may also be deemed inaccessible if there is less than 24 inches of clearance from the bottom of the floor joists to the surface below. If any area which has been reported as inaccessible is made accessible, the inspection company may be contacted for another inspection. An additional fee may apply.
- 4. Consumer Maintenance Advisory Regarding Integrated Pest Management for Prevention of Wood Destroying Insects. Any structure can be attacked by wood destroying insects. Homeowners should be aware of and try to eliminate conditions which promote insect infestation in and around their structure(s). Factors which may lead to wood destroying insect infestation include: earth to wood contact, foam insulation at foundation in contact with soil, faulty grade, improper drainage, firewood against structure(s), insufficient ventilation, moisture, wood debris in crawlspace, wood mulch or ground cover in contact with the structure, tree branches touching structure(s), landscape timbers and wood decay. Should these or other conditions exist, corrective measures should be taken in order to reduce the chances of infestation of wood destroying insects and the need for treatment.

5	Noither the increcting company per t	ha inenactor has had presently has	. or contemplates having any interest in the property i	inenactad