


B619 Iron Lake Saluda County

Duncan Rd, Saluda, SC, USA

98.0 Acres



B619 Iron Lake Saluda County

Soil Report

Symbol	Map Unit Description	Farmland class	Area (AC)	Available Water Storage (0-150cm - Weighted Average)	Flooding Frequency (Maximum)	Drainage Class (Dominant Condition)	Drainage Class (Wettest Component)	Hydric Classification	Water Table Depth (Annual Minimum)	Water Table Depth (April to June Minimum)	Bedrock Depth (Minimum)	Soil Order
HnC	Herdon silt loam, 6 to 10 percent slopes	Farmland of statewide importance	0	23.6	None	Well drained	Well drained	0	0	0	0	Ultisols
HnB	Herdon silt loam, 2 to 6 percent slopes	All areas are prime farmland	0	23.6	None	Well drained	Well drained	0	0	0	0	Ultisols
Mv	Mixed alluvial land	Prime farmland if drained and either protected from flooding or not frequently f	0	28.3	Occasional	Somewhat poorly drained	Somewhat poorly drained	0	31	31	0	Inceptisols
AmB	Alamance silt loam, 2 to 6 percent slopes	All areas are prime farmland	0	15.9	None	Moderately well drained	Moderately well drained	0	69	0	102	Ultisols
EkC3	Efland silty clay loam, 6 to 10 percent slopes, severely eroded	Not prime farmland	0	20.6	None	Well drained	Well drained	0	0	0	0	Alfisols