


B891 SC Greenwood County-Lorenzo Road

Lorenzo Rd, Greenwood, SC, USA

108.0 Acres



B891 SC Greenwood County-Lorenzo Road

Soil Report

Symbol	Map Unit Description	Farmland class	Area (AC)	Available Water Storage (0-150cm - Weighted Average)	Flooding Frequency (Maximum)	Drainage Class (Dominant Condition)	Drainage Class (Wettest Component)	Hydric Classification	Water Table Depth (Annual Minimum)	Water Table Depth (April to June Minimum)	Bedrock Depth (Minimum)	Soil Order
CaC	Cataula sandy loam, 6 to 10 percent slopes	Not prime farmland	0	14.8	None	Moderately well drained	Moderately well drained	0	89	89	0	Ultisols
EnD	Enon sandy loam, 10 to 15 percent slopes	Not prime farmland	0	20.2	None	Well drained	Well drained	0	0	0	0	Alfisols
CaB	Cataula sandy loam, 2 to 6 percent slopes	Farmland of statewide importance	0	14.8	None	Moderately well drained	Moderately well drained	0	89	89	0	Ultisols
WkD	Wilkes fine sandy loam, 6 to 15 percent slopes	Not prime farmland	0	6.2	None	Well drained	Well drained	0	0	0	38	Alfisols
WkF	Wilkes sandy loam, 15 to 40 percent slopes	Not prime farmland	0	6.5	None	Well drained	Well drained	0	0	0	68	Alfisols
WkD	Wilkes sandy loam, 6 to 15 percent slopes	Not prime farmland	0	6.5	None	Well drained	Well drained	0	0	0	68	Alfisols
CeC2	Cecil sandy clay loam, 6 to 10 percent slopes, eroded	Not prime farmland	0	21.0	None	Well drained	Well drained	0	0	0	0	Ultisols
EnC	Enon sandy loam, 6 to 10 percent slopes	Not prime farmland	0	20.9	None	Well drained	Well drained	0	0	0	0	Alfisols
CcC2	Cataula sandy clay loam, 6 to 10 percent slopes, eroded	Not prime farmland	0	19.2	None	Moderately well drained	Moderately well drained	0	64	64	0	Ultisols
Ch	Chewacla loam, 0 to 2 percent slopes, frequently flooded	Prime farmland if protected from flooding or not frequently flooded during the g	0	26.9	Frequent	Somewhat poorly drained	Somewhat poorly drained	5	25	0	0	Inceptisols