


Notes

- 1) This is a HIGH INTENSITY soils investigation.

2) THIS IS A SKETCH MAP. THE MAPPED AREAS ARE ONLY GENERALLY LOCATED ON THIS SKETCH. PIN FLAGS WERE PLACED AND MEASURED IN THE FIELD AND MUST BE FOUND IN PLACE.



I, Norman Marable, affirm that this soil map meets the standards established in the Regulations to Govern Subsurface Sewage Disposal, the Soils Handbook, and the Soil Taxonomy. No other warranties are made or implied.

Legend

- Legend
- mpi - estimated minutes per rock
 - $\geq$ - greater than or equal to
 - $>$ - greater than
 - Dist. - DISTURBED $\rightarrow$ 75 mpi
 - $\cdots \rightarrow$ - DRAINAGEWAY
MAINTAIN A 15 foot setback
 -  - DRAINAGEWAY wider than 10 feet
maintain a 15-20 foot setback - AS shown
 - H-H - Humphreys - Harpeth S. 15' /
45 MPI TO 26" Rock $\geq$ 36"




Norman Marable
Soils Consultant
P.O. Box 481
Columbia, TN 38402

Signature of Soil consultant
does not constitute approval of
this map by the Division of
Water Resources.

For: Alexis Monsivais

ANY CUTTING, FILLING OR
COMPACTION WILL VOID THIS
SOIL MAP. HEAVY TRAFFIC MAY
CAUSE COMPACTION.



Hicks Lane