
PARSON TILE & BACKHOE SERVICE, INC.

PO Box 101 305 North Center Street Ionia, IA 50645

394-3367



South of House

6" clay
6" plastic
5" clay
5" plastic
4" plastic

All clay lines are hand dug 60' spacing

NAME Cecelia Schimmel Everett Shinstine

Section. 25 Township Chickasaw County. Chickasaw


Contractor ..... Date Installed. 10-2002

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

PARSON TILE & BACKHOE SERVICE, INC.

PO Box 101 305 North Center Street Ionia, IA 50645

394-3367



6" clay

5" clay hand dug

5" plastic

4" plastic

x x x fence

intake

abandon 5" clay

60' spacing

NAME Cecelia Schimmel Everett Shinstine

Section 26 Township Chickasaw County Chickasaw


Contractor ..... Date Installed May 2002

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

PARSON TILE & BACKHOE SERVICE, INC.

PO Box 101 305 North Center Street Ionia, IA 50645

394-3367



NAME Cecelia Schimmel Everett Shinstin

Section 25 Township Chickasaw County Chickasaw


Contractor ..... Date Installed 10-2002

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

PARSON TILE & BACKHOE SERVICE, INC.

PO Box 101 305 North Center Street Ionia, IA 50645

394-3367



6" clay

5" clay hand dug

5" plastic

4" plastic

x x x fence

intake

abandon 5" clay

30' spacing

NAME Cecelia Schimmel Everett Shinstin

Section 26 Township Chickasaw County Chickasaw


Contractor ..... Date Installed May 2002

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

PARSON TILE & BACKHOE SERVICE, INC.

PO Box 101 305 North Center Street Ionia, IA 50645

394-3367



hand dug 6" clay

6" plastic

5" plastic

5" clay hand dug

4" plastic

missing lines

60' spacing


NAME Cecelia Schimmel Everett Shinstine

Section 25 Township Chickasaw County Chickasaw

Contractor ..... Date Installed 4-2002

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

TILE RECORD MAP



NAME Evert Shinstine

Section 25 Township Chickasaw County Chickasaw


Contractor _____ Date Installed Aug 93

Amount of Tile Installed: 3" _____ 4" _____ 5" _____

6" _____ 8" _____ Larger _____

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

PAT FINNEGAN CONSTRUCTION CO., IONIA, IOWA 50645



NAME Evert Shinstine

Section 25 Township Chickasaw County Chickasaw

Contractor _____ Date Installed Aug 93

Amount of Tile Installed: 3" _____ 4" _____ 5" _____

6" _____ 8" _____ Larger _____

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

PAT FINNEGAN CONSTRUCTION CO., IONIA, IOWA 50645