

DESCRIPTION

Being a tract of land situated in the J.C. Bailey Survey, Abstract No. 83 and the J. Harris Survey, Abstract No. 502, Cooke County, Texas and being colled Lot 37, of River Ridge Estates, an Addition to Cooke County, Texas, according to the Map or Plat thereof recorded in/under Cabinet A, Side 46, of the Plat Records of Cooke County, Texas. and being more particularly described herein as follows:

and a 1/2 inch iron rod found on the West side of F.M. Road 2382 (a public road) teast corner of a called Lot 38A of

River Ridge Estates, according to the Map or Plat thereof recorded in/under Cabinet A, Slide 124, of said Plat Records;

THENCE South 23 degrees 12 minutes 38 seconds West, with the East line of said Lot 37 and the West line of said F.M. Road 2382, along or near a fence, a distance of 1225.44 feet to a 1/2 inch iron rod found for the Southeast corner of said Lot 37 and the Northeast corner of a called Lot 36, said River Ridge Estates (said Cabinet A, Slide 46);

THENCE North 62 degrees 21 minutes 55 seconds West, with the South line said Lot 37 and the North line said Lot 36, a distance of 1626.08 feet to a 1/2 inch iron rod found for the Southwest corner said Lot 37, the Northwest corner said Lot 36, the Northeast corner of a called Lot 40, said River Ridge Estates (said Cabinet A, Slide 46) and the Southeast corner of a called Lot 39, said River Ridge Estates (said Cabinet A, Slide 46);

349.28 feet to a 1/2 inch iron iron said Lot 37 and the Northwest corner of said Lot 37 and the Northwest corner of said Lot 37 and the North line said Lot 37 and THENCE North 89 degrees 16 minutes 48 seconds East, with the North line said Lot 37 and the South line said 38A, a distance of 1896.24 feet to the **POINT OF BEGINNING** and containing, within the metes and bounds herein recited, 30.375 acres of land, more or less. line said Lot 39, passing at a distance of 62.75 feet a 4 inch steel fence post for and continuing along said course, along or near a fence for a total distance of set to a 1/2 inch iron rod found near a 4 inch steel fence post in the South line 38.4 for the Northwest corner of said Lot 37 and the Northeast corner said Lot 39;

SURVEYOR'S CERTIFICATION

certify that, under my personal supervision, a careful survey was made on the fithe property shown hereon. This survey was prepared without the benefit of a fit ereport. USE OF THIS SURVEY FOR ANY OTHER PURPOSE OR BY OTHER PARTIES AT THEIR RISK AND THE UNDERSIGNED IS NOT RESPONSIBLE TO OTHERS FOR ANY ULTING THEREFROM. The plat hereon is a careful representation of the subject as determined by an on-the-ground survey, the lines and dimensions of said being as indicated by the platt, the size, location and type of buildings and ents being as shown, the improvements being within the boundary of the property, rom property lines the distance indicated and that the distance from the nearest any street or road being as shown on said plat. EXCEPT AS SHOWN THERE ARE NO TRINSIONS APPARENT ON THE GROUND street or road being as shown on said plat. EXCEPT , ISIONS OR PROTRUSIONS APPARENT ON THE GROUND.

GHN, JR PROFESSIONAL LAND SURVEYOR NO. 5926 27, 2022



LAND TITLE SURVEY

RIVER RIDGE ESTATES

J.C. BAILEY SURVEY, A-83 AND

J. HARRIS SURVEY, A-502

COOKE COUNTY, TEXAS 2525 F.M. 2382 **LOT 37**

AS SHOWN

2525 FM 2382

9/27/22 그 유 1

JCV WDJ