

STATE OF TEXAS WELL REPORT for Tracking #638945

Owner:	Chad Koonce	Owner Well #:	No Data
Address:	near the intersection of FM 2027 and FM 979 near CR 271A Maysfield, TX 76520	Grid #:	59-02-2
Well Location:	near the intersection of FM 2027 and FM 979 near CR 271A Maysfield, TX 76520	Latitude:	30° 58' 49.44" N
		Longitude:	096° 48' 08.1" W
		Elevation:	362 ft. above sea level
Well County:	Milam		

Type of Work:	New Well	Proposed Use:	Domestic
---------------	-----------------	---------------	-----------------

Drilling Start Date: **1/13/2023** Drilling End Date: **1/16/2023**

	Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)
Borehole:	8.75	0	277

Drilling Method: **Mud (Hydraulic) Rotary**

Borehole Completion: **Filter Packed; Screened; Straight Wall**

	Top Depth (ft.)	Bottom Depth (ft.)	Filter Material	Size
Filter Pack Intervals:	221	277	Sand	12/20

	Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
Annular Seal Data:	0	10	Concrete 10 Bags/Sacks
	206	221	Bentonite 4 Bags/Sacks

Seal Method: **Poured**

Distance to Property Line (ft.): **78**

Sealed By: **Driller**

Distance to Septic Field or other concentrated contamination (ft.): **N/A**

Distance to Septic Tank (ft.): **N/A**

Method of Verification: **tape**

Surface Completion:	Surface Sleeve Installed	Surface Completion by Driller
---------------------	---------------------------------	--------------------------------------

Water Level: **115 ft. below land surface on 2023-01-13**

Packers: **No Data**

Type of Pump:	Submersible	Pump Depth (ft.): 200
---------------	--------------------	------------------------------

Well Tests:	Jetted	Yield: 20+ GPM
-------------	---------------	-----------------------

Water Quality:

Strata Depth (ft.)	Water Type
No Data	No Data

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which
contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Williams Water Wells LLC**

**1165 Hwy. 14
Kosse, TX 76653**

Driller Name: **Johnny R. Williams**

License Number: **2854**

Apprentice Name: **Justin Ray Williams**

Apprentice Number: **60134**

Comments: **No Data**

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	10	clay
10	15	sandy clay
15	16	clay
16	20	rock
20	76	clay, sand seams
76	93	sandy shale
93	144	sand
144	156	shale
156	193	sandy shale, coal
193	237	shale
237	240	sand
240	252	sand, sandy shale
252	277	sand
277	280	coal
280	285	shale

Casing:
BLANK PIPE & WELL SCREEN DATA

Dia (in.)	Type	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
4	Blank	New Plastic (PVC)	40	0	237
4	Screen	New Plastic (PVC)	40 0.020	237	277

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540