





No.	Revision/Issue	Date

Prepared by
**CORNER POST /
LAND SURVEYING, PLLC**
364 Spraguetown Road
Greenwich, New York 12834
Tel./Fax No. 518-892-2435
Website: www.CornerPostLandSurvey.com

SURVEY OF LANDS
FOR
PAUL AND LINDA
CHURCH
Situates in the Town of Greenwich
Washington County, New York.

Job No.	2016-004	2	Street
Date	FEB. 26, 2016		
Scale	1" = 100'		



Address: 851 COUNTY ROUTE 77
CENERY CEMETERY TO PAUL AND UNCA CHURCH.

THIS MAP AND SURVEY HAS BEEN PREPARED IN
CONFORMANCE WITH THE EXISTING CODE OF PRACTICE,
AND THE NEW YORK STATE ASSOCIATION OF PROFESSIONAL
LAND SURVEYORS.

Matthew C. Van Buren
MATTHEW C. VAN BUREN - P.L.S. REG. NO. 005940
I HEREBY CERTIFY THAT THE FOREGOING MAP AND SURVEY
WAS PREPARED BY ME OR UNDER MY CLOSE PERSONAL
SUPERVISION AND THAT I AM A LICENSED PROFESSIONAL
LAND SURVEYOR IN THE STATE OF NEW YORK.



DEED REFERENCES:

BOOK 3414 OF DEEDS AT PAGE 216, DATED MARCH, 14, 2014, LINDA CHURCH 1/K/a LINDA REESE TO LINDA AND PAUL CHURCH.

BOOK 3414 OF DEEDS AT PAGE 219, DATED MARCH 14, 2014, LINDA CHURCH 1/K/a LINDA REESE TO LINDA AND PAUL CHURCH.

BOOK 889 OF DEEDS AT PAGE 106, DATED MAY 29, 2001, THE TOWN OF GREENWICH TO COUNTY OF WASHINGTON.

LEGEND:

—	OVERHEAD WIRES
—	STONE WALL
—	WIRE FENCE LINE
—	FOUND IRON AXLE
—	FOUND IRON PIPE
—	FOUND IRON ROD
—	FOUND CAPPED IRON ROD
—	SET CAPPED IRON ROD
—	FOUND CONCRETE MONUMENT
—	UTILITY POLE
—	UTILITY RISER/BOX
—	CONIFEROUS TREE WITH FENCE
—	DECIDUOUS TREE WITH FENCE
—	TEST PIT
—	CHAN LINK FENCE LINE
—	WOOD FENCE LINE
—	EDGE OF WOODS
—	TREE STUMP WITH FENCE
—	WELL
—	WATER VALVE
—	WATER SHUT OFF
—	FIRE HYDRANT
—	GAS VALVE
—	CATCH BASIN
—	SEWER MANHOLE
—	DRAINAGE MANHOLE

[illegible][illegible]