

PROPERTY LOCATED AT: 438 Sandy Beach Road, Danforth, ME 04424

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I – WATER SUPPLY

TYPE OF SYSTEM: ☐ Public ☐ Private ☐ Seasonal _____ ☐ Unknown
☐ Drilled ☐ Dug ☒ Other from lake, year round use

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the
(public/private/other) water system?

Pump (if any): ☐ N/A ☐ Yes ☒ No ☐ Unknown

Quantity: ☐ Yes ☒ No ☐ Unknown

Quality: ☐ Yes ☐ No ☒ Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? ☐ Yes ☒ No

~~If Yes, Date of most recent test: _____ Are test results available? .. ☐ Yes ☐ No~~

~~To your knowledge, have any test results ever been reported as unsatisfactory
or satisfactory with notation? ☐ Yes ☐ No~~

~~If Yes, are test results available? ☐ Yes ☐ No~~

~~What steps were taken to remedy the problem? _____~~

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: Lake

Installed by: Owner

Date of Installation: 1999

USE: Number of persons currently using system: 2

Does system supply water for more than one household? ☐ Yes ☒ No ☐ Unknown

Comments: System located in crawl space, pump in lake, buried underground in 2006 by Micah Bartlett

Source of Section I information: Sellers

Buyer Initials _____

Page 1 of 7

Seller Initials RSA BMA

SECTION II — WASTE WATER DISPOSAL

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Quasi-Public _____ ☐ Unknown

~~IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):~~

~~Have you had the sewer line inspected?.....~~ ☐ Yes ☐ No

~~If Yes, what results:_____~~

~~Have you experienced any problems such as line or other malfunctions?.....~~ ☐ Yes ☐ No

~~What steps were taken to remedy the problem?_____~~

IF PRIVATE (Strike Section if Not Applicable):

Tank: ☒ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other: _____

Tank Size: ☐ 500 Gallon ☒ 1000 Gallon ☐ Unknown ☐ Other: _____

Tank Type: ☒ Concrete ☐ Metal ☐ Unknown ☐ Other: _____

Location: by driveway & steps entering porch OR ☐ Unknown

Date installed: 1997+- Date last pumped: None Name of pumping company: None

Have you experienced any malfunctions? ☒ Yes ☐ No

If Yes, give the date and describe the problem: Replaced pump

~~Date of last servicing of tank: _____ Name of company servicing tank: _____~~

Leach Field: ☒ Yes ☐ No ☐ Unknown

If Yes, Location: Between camp & road

Date of installation of leach field: Unknown Installed by: Unknown

Date of last servicing of leach field: None Company servicing leach field: None

Have you experienced any malfunctions? ☐ Yes ☒ No

~~If Yes, give the date and describe the problem and what steps were taken to remedy:_____~~

Do you have records of the design indicating the # of bedrooms the system was designed for? ☐ Yes ☒ No

If Yes, are they available? ☒ Yes ☐ No

Is System located in a Shoreland Zone? ☒ Yes ☐ No ☐ Unknown

Comments: _____

Source of Section II information: Sellers

Buyer Initials _____

Page 2 of 7

Seller Initials RJA BJA

SECTION III – HEATING SYSTEM(S)/HEATING SOURCES(S)

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S)	Empire Propane			
Age of system(s) or source(s)	1999			
Name of company that services system(s) or source(s)	Dead River			
Date of most recent service call	Around 5 years ago			
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	150 gallons			
Malfunction per system(s) or source(s) within past 2 years	None			
Other pertinent information	None			

Are there fuel supply lines? ☒ Yes ☐ No ☐ Unknown
 Are any buried? ☐ Yes ☒ No ☐ Unknown
 Are all sleeved? ☒ Yes ☐ No ☐ Unknown
 Chimney(s): ☒ Yes ☐ No
 If Yes, are they lined: ☒ Yes ☐ No ☐ Unknown
 Is more than one heat source vented through one flue? ☐ Yes ☒ No ☐ Unknown
 Had a chimney fire: ☐ Yes ☒ No ☐ Unknown
 Has chimney(s) been inspected? ☐ Yes ☒ No ☐ Unknown

~~If Yes, date:~~ _____

Date chimney(s) last cleaned: **Propane Use-Unknown**

Direct/Power Vent(s): ☐ Yes ☒ No ☐ Unknown
 Has vent(s) been inspected? ☐ Yes ☒ No ☐ Unknown

~~If Yes, date:~~ _____

Comments: _____

Source of Section III information: **Sellers**

SECTION IV – HAZARDOUS MATERIAL

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? ☐ Yes ☒ No ☐ Unknown

~~If Yes, are tanks in current use? ☐ Yes ☐ No ☐ Unknown~~

~~If no longer in use, how long have they been out of service? _____~~

~~If tanks are no longer in use, have tanks been abandoned according to DEP? ☐ Yes ☐ No ☐ Unknown~~

~~Are tanks registered with DEP? ☐ Yes ☐ No ☐ Unknown~~

~~Age of tank(s): _____ Size of tank(s): _____~~

~~Location: _____~~

Buyer Initials _____

Page 3 of 7

Seller Initials **CSA BMA**

PROPERTY LOCATED AT: 438 Sandy Beach Road, Danforth, ME 04424

~~What materials are, or were, stored in the tank(s)?~~

~~Have you experienced any problems such as leakage?~~ ☐ ~~Yes~~ ☒ ~~No~~ ☐ ~~Unknown~~

~~Comments:~~ _____

Source of information: Sellers

B. ASBESTOS — Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? ☐ Yes ☒ No ☐ Unknown

In the ceilings? ☐ Yes ☒ No ☐ Unknown

In the siding? ☐ Yes ☒ No ☐ Unknown

In the roofing shingles? ☐ Yes ☒ No ☐ Unknown

In flooring tiles? ☐ Yes ☒ No ☐ Unknown

Other: _____ ☐ Yes ☒ No ☐ Unknown

~~Comments:~~ _____

Source of information: Sellers

C. RADON/AIR - Current or previously existing:

Has the property been tested? ☐ Yes ☒ No ☐ Unknown

~~If Yes: Date: _____ By: _____~~

~~Results:~~ _____

~~If applicable, what remedial steps were taken?~~ _____

~~Has the property been tested since remedial steps?~~ ☐ ~~Yes~~ ☐ ~~No~~ ☐ ~~Unknown~~

~~Are test results available?~~ ☐ ~~Yes~~ ☐ ~~No~~

~~Results/Comments:~~ _____

Source of information: Sellers

D. RADON/WATER - Current or previously existing:

Has the property been tested? ☐ Yes ☒ No ☐ Unknown

~~If Yes: Date: _____ By: _____~~

~~Results:~~ _____

~~If applicable, what remedial steps were taken?~~ _____

~~Has the property been tested since remedial steps?~~ ☐ ~~Yes~~ ☐ ~~No~~ ☐ ~~Unknown~~

~~Are test results available?~~ ☐ ~~Yes~~ ☐ ~~No~~

~~Results/Comments:~~ _____

Source of information: Sellers

E. METHAMPHETAMINE - Current or previously existing:

☐ Yes ☒ No ☐ Unknown

~~Comments:~~ _____

Source of information: Sellers

Buyer Initials _____

Page 4 of 7

Seller Initials RJA BJA

PROPERTY LOCATED AT: 438 Sandy Beach Road, Danforth, ME 04424

F. LEAD-BASED PAINT/PAINT HAZARDS — (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
..... ☐ Yes ☒ No ☐ Unknown ☐ Unknown (but possible due to age)

~~If Yes, describe location and basis for determination:~~ _____

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☒ No

If Yes, describe: _____

Are you aware of any cracking, peeling or flaking paint? ☐ Yes ☒ No

~~Comments:~~ _____

Source of information: Sellers

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL: ☐ Yes ☒ No ☐ Unknown

LAND FILL: ☐ Yes ☒ No ☐ Unknown

RADIOACTIVE MATERIAL: ☐ Yes ☒ No ☐ Unknown

~~Other:~~ _____

Source of information: Sellers

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V — GENERAL INFORMATION

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ☒ Yes ☐ No ☐ Unknown

If Yes, explain: Road association, encroachment-abutting owner's driveway on small portion of our land

Source of information: Sellers

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ☐ Yes ☒ No ☐ Unknown

If No, who is responsible for maintenance? Road Association

Road Association Name (if known): East Grand Lake Association

Buyer Initials _____

Page 5 of 7

Seller Initials RJA BJA

PROPERTY LOCATED AT: 438 Sandy Beach Road, Danforth, ME 04424

Are there any tax exemptions or reductions for this property for any reason including but not limited to:
Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....

☐ Yes ☒ No ☐ Unknown

If Yes, explain: _____

Is a Forest Management and Harvest Plan available?..... ☐ Yes ☒ No ☐ Unknown

Is house now covered by flood insurance policy (not a determination of flood zone) ☐ Yes ☒ No ☐ Unknown

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish,
water filtration system, photovoltaics, wind turbines): Type: Propane Tanks, Satellite Dish

Year Principal Structure Built: 1990

What year did Seller acquire property? 1999

Roof: Year Shingles/Other Installed: 2001 (Metal)

Water, moisture or leakage: No

Comments: _____

Foundation/Basement:

Is there a Sump Pump? ☐ Yes ☒ No ☐ Unknown

Water, moisture or leakage since you owned the property: ☐ Yes ☒ No ☐ Unknown

Prior water, moisture or leakage? ☐ Yes ☐ No ☒ Unknown

Comments: _____

Mold: Has the property ever been tested for mold? ☐ Yes ☒ No ☐ Unknown

If Yes, are test results available? ☐ Yes ☒ No

Comments: _____

Electrical: ☐ Fuses ☒ Circuit Breaker ☐ Other: _____ ☐ Unknown

Comments: _____

Has all or a portion of the property been surveyed? ☒ Yes ☐ No ☐ Unknown

If Yes, is the survey available? ☒ Yes ☐ No ☐ Unknown

Manufactured Housing – Is the residence a:

Mobile Home ☐ Yes ☒ No ☐ Unknown

Modular ☐ Yes ☒ No ☐ Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure

..... ☐ Yes ☒ No ☐ Unknown

Comments: _____

~~KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may
have an adverse impact on health/safety:~~ _____

Comments: _____

Source of Section V information: Sellers

Buyer Initials _____

Page 6 of 7

Seller Initials RJA BYA

PROPERTY LOCATED AT: 438 Sandy Beach Road, Danforth, ME 04424

SECTION VI — ADDITIONAL INFORMATION

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ☐ Yes ☒ No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

<u>Robert J. Arsenault</u>	<u>10/26/2022</u>	<u>Bonnie M. Arsenault</u>	<u>10/26/2022</u>
SELLER	DATE	SELLER	DATE
Robert J. Arsenault		Bonnie M. Arsenault	

SELLER	DATE	SELLER	DATE
--------	------	--------	------

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER	DATE	BUYER	DATE
-------	------	-------	------

BUYER	DATE	BUYER	DATE
-------	------	-------	------

