

STATE OF TEXAS WELL REPORT for Tracking #478306

Owner: **Eric Elkins**

Owner Well #: **No Data**

Address: **1258 CR 146
Talpa, TX 76882**

Grid #: **42-11-5**

Well Location: **Co Rd 416
Coleman, TX 76834**

Latitude: **31° 48' 55" N**

Longitude: **099° 40' 08" W**

Well County: **Coleman**

Elevation: **No Data**

Type of Work: **New Well**

Proposed Use: **Domestic**

Drilling Start Date: **3/3/2017**

Drilling End Date: **3/3/2017**

Borehole:

<i>Diameter (in.)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
8	0	70

Drilling Method: **Air Rotary**

Borehole Completion: **Filter Packed**

Filter Pack Intervals:

<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Filter Material</i>	<i>Size</i>
15	70	Gravel	.375

Annular Seal Data:

<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Description (number of sacks & material)</i>
-2	15	Cement 12 Bags/Sacks

Seal Method: **Poured**

Distance to Property Line (ft.): **300**

Sealed By: **Driller**

Distance to Septic Field or other
concentrated contamination (ft.): **N/a**

Distance to Septic Tank (ft.): **N/a**

Method of Verification: **Stepped**

Surface Completion: **Surface Sleeve Installed**

Surface Completion by Driller

Water Level: **27 ft. below land surface on 2017-03-03**

Packers: **No Data**

Type of Pump: **No Data**

Well Tests: **Estimated** **Yield: 10 GPM**

Water Quality:

Strata Depth (ft.)	Water Type
34 - 70	Fresh

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which
contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **LANGE DRILLING CO**
BOX 283
ROWENA, TX 76875

Driller Name: **Pat Lange**

License Number: **2343**

Comments: **No Data**

Report Amended on 5/3/2018 by Request #24995

Report Amended on 6/5/2018 by Request #25201

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	19	Yellow Sandstone
19	30	Yellow Clay
30	34	Sugar Sand
34	41	Yellow Sandstone (Water 10gpm @ 34 ft)
41	54	Red Clay
54	62	Yellow Limestone
62	70	Red Shale

Casing:
BLANK PIPE & WELL SCREEN DATA

Dia (in.)	Type	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
5	Blank	New Plastic (PVC)	40	-2	70
	Mill Slot		0.035	20	70

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540