

STATE OF TEXAS WELL REPORT for Tracking #655206

Owner:	Renewed Land Group LTD	Owner Well #:	No Data
Address:	3030 W Beauregard Ave San Angelo , TX 76901	Grid #:	19-57-1
Well Location:	Henderson Ranch Rd T-1 Joplin, TX 76486	Latitude:	33° 06' 32.53" N
		Longitude:	097° 59' 52.97" W
Well County:	Jack	Elevation:	1085 ft. above sea level

Type of Work:	New Well	Proposed Use:	Domestic
---------------	-----------------	---------------	-----------------

Drilling Start Date: **5/4/2023** Drilling End Date: **5/4/2023**

	<i>Diameter (in.)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
Borehole:	7.875	0	160

Drilling Method: **Air Rotary**

Borehole Completion: **Filter Packed**

	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Filter Material</i>	<i>Size</i>
Filter Pack Intervals:	10	160	Gravel	3/8"

	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Description (number of sacks & material)</i>
Annular Seal Data:	0	6	Cement 2 Bags/Sacks
	6	10	Bentonite 3 Bags/Sacks

Seal Method: **Poured**

Distance to Property Line (ft.): **100+**

Sealed By: **Driller**

Distance to Septic Field or other
concentrated contamination (ft.): **Not Present**

Variance Number: **NA**

Distance to Septic Tank (ft.): **Not Present**

Method of Verification: **Visual**

Surface Completion:	Surface Sleeve Installed	Surface Completion by Driller
---------------------	---------------------------------	--------------------------------------

Water Level: **No Data**

Packers: **No Data**

Type of Pump: **No Data**

Well Tests: **Estimated** **Yield: 2.5 GPM**

Water Quality:

<i>Strata Depth (ft.)</i>	<i>Water Type</i>
No Data	No Data

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which
contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Erwin Water Well Drilling**
6991 FM 4
Jacksboro, TX 76458

Driller Name: **Robert Brent Erwin**

License Number: **60444**

Comments: **Drilled for Chad Koonce**

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

<i>Top (ft.)</i>	<i>Bottom (ft.)</i>	<i>Description</i>
0	2	Sandy Top Soil
2	5	Sandy Clay
5	17	Sand & Yellow Clay
17	35	Red & Yellow Clay
35	83	Sand
83	89	Red Clay
89	115	Sand
115	124	Red & Gray Clay
124	138	Sand
138	160	Gray Shale

Casing:
BLANK PIPE & WELL SCREEN DATA

<i>Dia (in.)</i>	<i>Type</i>	<i>Material</i>	<i>Sch./Gage</i>	<i>Top (ft.)</i>	<i>Bottom (ft.)</i>
4	Blank	New Plastic (PVC)	40	0	140
4	Perforated or Slotted	New Plastic (PVC)	40 0.020	140	160

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

**Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540**