




PLANNING AND ZONING DEPARTMENT

Suite 4, 401 Adams ST

FRIENDSHIP, WI 53934
www.co.adams.wi.us

PHONE: 608-339-4222

SEPTIC SYSTEM MAINTENANCE NOTICE
Deadline for Report Submittal – Monday, June 30, 2025



Tuesday, April 1, 2025

Our records indicate that it has been three (3) years since your septic system has been pumped and/or inspected. Maintenance of these systems involves having the system visually inspected every 3 years and having the tank(s) pumped if sludge and scum occupy more than 1/3 of the tank volume. Every time a septic system is inspected, maintained or serviced a report must be submitted electronically to the department by your servicing provider on your behalf.

Give this form to your servicing provider so they have all the necessary information to successfully report the servicing activity. **If they choose to submit the paper form to our office, there will be a \$10 filing fee and the servicing provider must sign, date and provide their current licensure for verification on this form.**

*Called Kuschner
4/14/25*

Owner Name: SUE SCHUETZ LIVING TRUST
Parcel ID #: 012015190000
Issue #: 5848 Year: 1977
Property Address: 257 BIRCH ST

Tank #1:

Gallons: undefined **Manufacturer:** undefined **Material Source:** undefined
Tank Type: undefined

Tank #2 (if applicable):

Gallons: undefined **Manufacturer:** undefined **Material Source:** undefined
Tank Type: undefined

Tank #3 (if applicable):

Gallons: undefined **Manufacturer:** undefined **Material Source:** undefined
Tank Type: undefined

System Type: Not Assigned

Gallons Pumped _____

Tank/Drain Field Inspection		
Surface Discharge Observed	Yes	No
Water Observed in Vent Pipe	Yes	No
System Functioning Properly	Yes	No