


CON-STRUCT, INC.
 1710 E. Main, P.O. Box 658
 Marshalltown, Iowa 50158
 Phone 515/752-1865



NAME LOYD BEDINGTON

Section _____ Township _____ County STORY

Contractor Roll Smith Date Installed NOV. 1986

Amount of Tile Installed: 5" 1734' 6" _____ 8" _____
 10" _____ 12" _____ Larger _____

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.