
NEA Soil Solutions

Darrell Gann
(870)-219-2107

RE: 19019 Raby Rd
Harrisburg, AR

SOIL ANALYSIS REPORT

On Wednesday, Feb 12th, I performed a soil analysis inspection at this address. I was provided with a photo of a house site plan from the potential buyer. Soil pits were dug on the indicated site to evaluate the soil for a potential new septic system. Multiple test pits were dug on different grades to check for hydro conductivity and redox features. The clay content was slightly high in the upper 24 inches of soil, but with a sandy gravel base in each hole, it is my opinion that there is adequate land and space to accommodate a septic system.

Based on my observations, the soil in these pits meets the ADH requirements for a residential septic system. This in no way guarantees future ADH approval without a permit submission and EHS approval .

Darrell Gann

ADH Designated Representative #ADH13846041

ADH Advanced Septic Installer #ADH13846041

ADH Certified Monitoring Personnel #ADH13846041