DS

10098

Stevenson Service Plumbing, Inc.

P.O. Box 140511 • Broken Arrow, OK 74014
918-925-2964 • stevesspinc@yahoo.com

JOB INVOICE

DATE ORDERED:	ORDER TAKEN BY:
PHONE NO.:	CUSTOMER ORDER #:
JOB LOCATION:	
JOB PHONE:	STARTING DATE:
TERMS:	

SOLD TO: David Golzar
ADDRESS: 4307 S Hickory
Broken Arrow
ATTENTION: Realtor: Cindy Rogers

QTY.	MATERIAL	UNIT	AMOUNT
	bill out		
	TOTAL MATERIALS:		

DESCRIPTION OF WORK

- perform a water leak test on drain system
- located, uncovered cleanout, prepared to do a test; unable to perform – meter locked
- 7/18 – realtor confirm water was on, came back to perform test; system held

MISCELLANEOUS CHARGES

~~fee~~ with no leaks
Realtor has pices just under 10 min mark and when it finished

TOTAL MISCELLANEOUS:

LABOR	TIME IN	TIME OUT	TOTAL HRS.	RATE	AMOUNT
Jonathan	7/17		1		
Jonath	7/18		1.75		

TOTAL LABOR: 412.00

WORK ORDERED: 7/17; 7/18
DATE ORDERED:
DATE COMPLETED:

TOTAL LABOR:	412.00
TOTAL MATERIALS:	
TOTAL MISCELLANEOUS:	
SUBTOTAL:	
DISCOUNT:	
DIAGNOSTIC CHARGE:	
GRAND TOTAL:	412.00

CUSTOMER APPROVAL SIGNATURE _____

AUTHORIZED SIGNATURE _____