



Found 1" alum rod with 3" alum cap, set by Dennis Kramer, LS #856.

Found 2 1/2" alum pipe with alum. cap. see LP 2006-01

Found 1 1/2" iron pipe with Wheeler County Surveyor brass cap

Found ODOT brass cap set in concrete at PI stamped "636+80.9 PI" which is N89°24'55"E, 2088.60 ft. from the SW corner of Section 25.

RECEIVED AND FILED

FEB 20 2006  
 DEPT. OF REVENUE  
 MET. REG. DIV.



Scale 1"=400'

**LEGEND**

- ⊙ Found monument as shown.
- ⊕ Set 5/8"x30" iron pin with attached 2" alum. cap marked with the appropriate corner designation and CORNERSTONE SURVEYING, INC.
- Set 5/8"x30" iron pin with attached red plastic cap marked CORNERSTONE SURVEYING, INC.
- ⊙ Set 2 1/2" aluminum pipe with attached 2 1/2" aluminum cap. See corner restoration records for details.
- X-X- Fence Line
- ( ) Record bearing and distance.

**NARRATIVE**

This survey was performed at the request of Aloha Medlock. The purpose of this survey was to establish certain lines of her property and mark a line for a proposed boundary adjustment.

This survey was performed using static GPS receivers and electronic total station. The bearings for this survey are based on the GPS survey. The GPS survey was made in NAD 83 State Plane Coordinates, Oregon North Zone. The state plane bearings were rotated clockwise 00°30'00" to true north near the SE corner of Section 25, T8S, R24E. All Bearings are relative to this local north meridian.

A search was made of the available records which pertain to this survey. Field measurements were made to locate the existing monuments and the fence lines shown. I found and accepted the monuments at the SE and SW corners of Section 25 and the monument at the NW corner of Section 24. I recovered and re-monumented the original corner stone monument at the NE corner of Section 25 and at the N1/4 corner of Section 26. I searched for the original monuments at the W1/4 corner of Section 24, the NW corner of Section 25 and at the four 1/4 corners of Section 25. No evidence of the original corner monuments was found. I established the NW corner of Section 25 at the double proportion position and set an aluminum monument. I established the 1/4 corner positions by single proportion. Section 25 was subdivided in the usual manner. I established and monumented the C1/4 corner, the CE1/16 corner, the CS1/16 corner and the S1/16 corner on the west boundary of Section 25. The proposed boundary adjustment line generally follows an existing fence line. Monuments were set along this line as directed by the land owners. The right of way line for State Highway No. 19 was established during the survey I completed for Wheeler County Land Partition No. 2006-01. I used the highway right of way determined in that survey and set a monument at the intersection with the proposed boundary adjustment line.

REGISTERED PROFESSIONAL LAND SURVEYOR  
*Jack L. Watson*  
 OREGON  
 SEPT 19, 1993  
 JACK L. WATSON  
 2734  
 Renewal Date 6/30/2006

**CORNERSTONE SURVEYING, Inc.**  
 233 S. Canyon Blvd., John Day, Oregon  
 (541) 575-1813

MAP OF SURVEY DEPENDENT RESURVEY OF SECTION 25 T8S, R24E, W.M. WHEELER COUNTY, OREGON	
SURVEYED FOR: Aloha Medlock	Date: 1/31/2006
SURVEYED BY: Jack Watson	
DRAWN BY: Jack Watson	